

HEX HEAD CAP SCREW - COARSE THREAD  
BRASS



1/4-20	5/16-18	3/8-16	7/16-14	1/2-13	5/8-11	3/4-10
1/2	1/2	1/2	2"	3/4	1"	1 1/2
5/8	5/8	5/8		7/8	1 1/4	1 3/4
3/4	3/4	3/4		1"	1 1/2	2"
7/8	7/8	7/8		1 1/4	1 3/4	
1"	1"	1"		1 1/2	2"	
1 1/4	1 1/4	1 1/4		1 3/4	2 1/4	
1 1/2	1 1/2	1 1/2		2"	2 1/2	
1 3/4	1 3/4	1 3/4		2 1/4	2 3/4	
2"	2"	2"		2 1/2	3"	
2 1/4	2 1/4	2 1/4		2 3/4	3 1/4	
2 1/2	2 1/2	2 1/2		3"	3 1/2	
2 3/4	2 3/4	2 3/4		3 1/2	3 3/4	
	3"	3"		4"	4 1/2	
		3 1/2		4 1/2	6"	
				6"		